

## Report of Thorough Inspection and/or Load Test Safety, Health and Welfare at Work (General Application) Regulations November 2007 in relation to Work Equipment.

| Make | Model      | Identification No | Year of Manufacture |
|------|------------|-------------------|---------------------|
| CASE | CX 75 C SR | NGE6A1500         | 2017                |

| Tests Carried out    |   | Result |  |
|----------------------|---|--------|--|
| Thorough Examination | X | Pass   |  |
| Load Test            | X | Pass   |  |
| Visibility Check     | X | Pass   |  |

## Maximum Safe Working Load (KG): 820 KG (Refer to load chart)

| Sample Loads (KG)                       | Machine Configuration                      |
|---|--|
| 820 Kg                                  | on tracks @ 6.0 metres reach               |
| 860 Kg                                  | On tracks blade lowered @ 6.0 metres reach |
| Date of Last Test/Inspection (if known) | NEW MACHINE                                |

## Comments/Defects:

None noted

Machine in good order, mirrors, cameras and motion alarm fitted and working correctly

| Owners Name & Address:      | Shanowen Plant Hire, Dublin |
|-----------------------------|-----------------------------|
| Purpose of this Inspection: | Scheduled inspection        |

| Name: Brendan Cross                    | Qualification: Plant Fitter     |
|--|---------------------------------|
| Job Title: Service Engineer            | Employer: Jim Macadam Equipment |
| Address Where Carried out:             | Ballymount, Dublin              |
| Date Carried Out: 25/08/17             |                                 |
| Next Inspection Due Before: 25/08/2018 |                                 |
| Signed: R_ /                           | Date: 25/08/17                  |